


MeasurLink® STATMeasure Report

Report Date: 9/30/2014 4:20:51 PM
 Run ID: 05/23/2014 08:42:46
 Inspection Routine: SL-STD-514
 Start Date: 05/23/2014 09:23:25
 End Date: 09/11/2014 07:12:16

Subgroups: 1 - 64
 Process: Grinding
 Part ID: SL-STD-514
 Feature ID: Diameter
 Revision: Rev. 1



Diameter					
Subgroup	Date Time	Obs 1	Subgroup	Date Time	Obs 1
1	5/23/2014 9:28:14 AM	0.312300	22	9/11/2014 6:59:37 AM	0.312350
2	5/23/2014 9:28:24 AM	0.312200	23	9/11/2014 7:02:15 AM	0.312300
3	5/23/2014 9:28:48 AM	0.312200	24	9/11/2014 7:02:15 AM	0.312300
4	5/23/2014 9:29:13 AM	0.312250	25	9/11/2014 7:02:16 AM	0.312300
5	5/23/2014 9:29:25 AM	0.312250			
6	5/23/2014 9:29:36 AM	0.312250			
7	5/23/2014 9:29:44 AM	0.312250			
8	5/23/2014 9:29:54 AM	0.312250			
9	5/23/2014 9:30:05 AM	0.312250			
10	5/23/2014 9:30:15 AM	0.312250			
11	5/23/2014 9:30:38 AM	0.312250			
12	5/23/2014 9:30:48 AM	0.312250			
13	5/23/2014 9:30:59 AM	0.312250			
14	5/23/2014 9:31:09 AM	0.312300			
15	5/23/2014 9:31:22 AM	0.312250			
16	5/23/2014 9:31:30 AM	0.312300			
17	9/11/2014 6:45:46 AM	0.312300			
18	9/11/2014 6:45:59 AM	0.312350			
19	9/11/2014 6:59:30 AM	0.312350			
20	9/11/2014 6:59:32 AM	0.312350			
21	9/11/2014 6:59:33 AM	0.312350			