


MeasurLink® STATMeasure Report

Report Date: 9/30/2014 4:20:51 PM
 Run ID: 05/23/2014 08:42:46
 Inspection Routine: SL-STD-514
 Start Date: 05/23/2014 09:23:25
 End Date: 09/11/2014 07:12:16

Subgroups: 1 - 64
 Process: Grinding
 Part ID: SL-STD-514
 Feature ID: Diameter
 Revision: Rev. 1



Subgroup	Date Time	Obs 1
51	9/11/2014 7:06:24 AM	0.312350
52	9/11/2014 7:06:26 AM	0.312350
53	9/11/2014 7:07:54 AM	0.312250
54	9/11/2014 7:07:55 AM	0.312250
55	9/11/2014 7:07:56 AM	0.312250
56	9/11/2014 7:07:57 AM	0.312250
57	9/11/2014 7:07:58 AM	0.312250
58	9/11/2014 7:11:46 AM	0.312350
59	9/11/2014 7:11:47 AM	0.312350
60	9/11/2014 7:11:50 AM	0.312350
61	9/11/2014 7:11:51 AM	0.312350
62	9/11/2014 7:11:53 AM	0.312350
63	9/11/2014 7:12:14 AM	0.312300
64	9/11/2014 7:12:16 AM	0.312300